





SECONDARY SINGLE-STORY MASS ATTACHED TO PRIMARY 2-STORY VOLUME



IRREGULAR BUILDING MASSING

DORMER WINDOWS ATTACHED TO PRIMARY ROOF

15	PHOTOGRAPHS COMMON DESIGN ELEMENTS WITH NEIGHBORHOOD CONTEXT	DRAWING ISSUE: INNOVATIVE HOUSING SUBMITTAL 06.15.2009	**IDYLWOOD** ROB GUNTHER, OWNER 17259 NE 36TH ST REDMOND, WA 98052
DRAWN BY: MS REVIEWED BY: SR			

JOHNSTON ARCHITECTS PLLC

100 NE Northlake Way, Suite 200 . Seattle, Washington 98105 www.johnstonarchitects.com ph 206.523.6150 fax 206.523.9382