


PERF-DRAIN
NTS

TIGHT-LINE
NTS

BOX W/ SECURED CARSON INDUSTRIES LID. MODEL 910-12B BLACK OR EQUAL. MARKED "STORM" OR "DRAIN"



CLEAN OUT
NTS

NOTES:

1. LATERALS TO LOTS: WYE TO LOT CAP AND MARK LOCATION WITH 2"X4" POST MARKED "STORM".
2. CLEAN OUT LOCATIONS TO BE AT BENDS, END OF LINES AND AT 75' OC MAX SPACING.